Dug pits 18x18x12 inches in each section and raised a mound around the corner. A 10" pine bears N84°30'W, 35 links. A 12" pine bears S02°E, 28 links. Found what I accepted as the original BT in Sec. 20. No other evidence Found: found since it was destroyed by an existing county road. DESCRIPTION OF MONUMENT AND ACCESSORIES ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER: Date of work: 5/74 At record bearing and distances from the BT in Sec. 20, I drove a 5/8" rebar into the asphalt and set a yellow cap stamped Sorenson & Company on the rebar. A 6" Ponderosa Pine bears N38°E, 51.8'. A 12" Ponderosa Pine bears S04°E, 77.5'. Both trees are blazed and scribed RM. SKETCH, WITH COURSE AND DISTANCE TO ADJACENT CORNERS IF DETERMINED IN THIS SURVEY. (MAY SKETCH OR PASTE REPRODUCTION ON REVERSE SIDE.) 6" Ponderosa Pine, blazed + scribed "RM" See Certificate of Survey #44. SEC COR 12" Ponderosa Pine, blazed & scribed "RM" DIAGRAM OF CORNER: David R. Davis Surveyor's Seal I, certify that the Jinformation shown herein is true and N. correct. TAN 12 AUR SEC SEC Signature of Ground Party Chief 18 17 RDON E. 130N Gordon E. Sorenson I. ... SEC SEC certify that I have carefully performed or reviewed the 19 20 ES work done on the diagrammed corner as reported on this recordation form and approve the same. R.26 W. T. 20 N GISTET • = Corner recorded on the sheet GR. & LAND Signature of Surveyor 2345ES Registration Number 2 MBK Office of Clerk and Recorder, County of Sanders 11:29 and This "corner record" was filed for record on the day of 19 was noted on the cross-index plat and is ussigned page No. 409, in book No. Standune County Official N-5 20N ORM 125-41483 26W Cross Index No. T R. Mer 1 PAGE 409 VOI.

CERTIFIED LAND CORNER RECORDATION

DESCRIPTION OF CORNER EVIDENCE FOUND, AND ORIGINAL RECORD (IF KNOWN)

Record: A post $4\frac{1}{2}$ feet x 2" square with a marked stone 12" in the ground.