61-241871

## CERTED TWID ODGUES DUDO BYNOL

## DESCRIPTION OF CORNER EVIDENCE FOUND, AND ORIGINAL RECORD (IF KNOWN)

FOUND: The broken remains of the original marked stone plainly visable. The original stone and piece were lying loose by a brace post. This post purportedly occupies the original corner position. The brace post is rotten at the base but still stands.

ORIGINAL RECORD: Set a slate stone, 18x12x6 inches, 12 inches in the ground, for the 1/4 corner, marked 1/4 on the west face; and raise a mound of stone, 2 ft base 1 1/2 ft. high west of corner.

DESCRIPTION OF MONUMENT AND ACCESSORIES ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF, THIS CORNER: Found Date of work: 6-2-78 14 Sec. Cor, Stone by brace post 20 Scale VO-SKETCH, WITH COURSE AND DISTANCE TO ADJACENT CORNERS-IF DETERMINED IN THIS SURVEY. (MAY SKETCH OR PASTE REPRODUCTION ON REVERSE SIDE.) 16 See cor. Set by Single Proportion A \$ 12 Rebar + Cap (BIA) 00 A Steel Rebar Set by Medland 19 20 PRIOR SURVEY; Found in Road 29 30 DIAGRAM OF CORNER: Surveyor's Seal I. .. T23N certify that the information shown herein is true and R20W correct. Signature of Ground Party Chief 19 ristopher Balstad Jr. certify that I have carefully performed or reviewed the work done on the diagrammed corner as reported on this recordation form and approve the same. = Corner recorded on the sheet Signature of Surveyor 3322 S Registration Number Atate Montan fice of Clerk and Recorder, County of O'CLOLK A.M. at 11:02 is "corner record" was filed for record on the 12 day of 19.72, was noted on the cross-index plat and is 24187<u>1</u> Ethel M. Harding, Clerk and Recorder -", in book No. C-804 igned Examine Hartbach, Deput, County OfficialBy: Cross Index No. P-5 T. 23 N R.20W Mer. n 125 - 45227