61-

372253

INSTRUCTIONS

Original and/or subsequent record used to evaluate the corner position.
Description of evidence found, note discrepancies in the record, state method in establishing lost or obliterated

corners.

Description of monument and accessories set to perpetuate the corner position
Sketch of corner, show all pertinent data which can best be shown in a soutch example, corner marking, topography lies, position of accessories, etc.

Certification must be signed and sealed by Land Surveyor registered in the State of Montana.
Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

Corner S.W. Sec. Cor. Section 17 T. 23N. R. 20W. P.M.M. LAKE County

RECORD: from G.L.O. Field Book 4599, page 24, surveyed April 1905

Set a slate stone, 18"x 14"x 8", 12" in the ground,

marked with 3 notches on so. and 5 notches on east edge, no BT's within limits.

On COS 2409 the intersection of N-S and West fence line was used, nothing was set. On Subdivision Plat #22 Balstad claims to have set this corner, nothing noted as to what was set.

- FOUND: No stone found. Found a bridge spike with washer, fits ties per Subdivision Plat #22.
- SET: Replaced the found bridge spike with a 5/8" rebar & 2" alum. cap marked as shown below, from which:

A 40d spike, up 0.3' on east side of RR tie fence post bears North 12.93'.

A 40d spike, up 0.4' on south side of a fence post bears West 27.17'.

Used a SILVA hand compass (declination 18⁰30'E)

REFERENCE C.O.S. ___ 5|49 2"ALUMINUM CAP BRIEN T23N R20W 18 17 19 20 ITA NA 5555 NONTANA 1995 768IS EXISTING FENCE ET 40d SPIKE UP 0.4 DANIEL SET 40d SPIKE UP 0.3 CERTIFICATION BRIEN ON SOUTH SIDE OF ENCE POST; (2nd POST ON EAST SIDE OF R.R. Daniel P. Brien TIE FENCE POST 7681S 18 certify the information shown herein is true and correct. SACK FROM CORNER NORTH - 12.93' Signature Ground Parly Chief ANI - 23.7' 19 20 Daniel P. Brien See. This SET 5/8" REBAR & certify that this Corner Record correctly represents work performed by me of under my direction in compliance with the "Corner Record tion Act" (2022-101) et sets 20/C.A.) WEST 2" ALUMINUM CAP 27.17' 1768/S))Uner Em Signalure of Surveyor & Seal -19.0' 19.8' Date: 8/14/95 Reg. No. 768/S EXISTING FENCE Employer: HERSMAN LAND SURVEY SKETCH OF CORNER LAKe Sec. /7 Office of Clerk and Recorder, County of _ . This "corner FEB 2 8 '96 ct 372253 record" was filed for record on _ 8:35 A.M was noted on the cross-index plat and is assigned RUTH E. HODGES 2010 by Jicki Riebe, Deputy nty Official N-5 <u>т. 23N. р. 20W. рмм</u> Index No. corner this sheet Adopted July 1, 1981, Montana Board o Jonal Engineers & Land Surveyors