INSTRUCTIONS

Original and/or subsequent record used to evaluate the corner position.
Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated corners.
Description of monument and accessories set to perpetuate the corner position.
Sketch of corner, show all pertinent data which can best be shown in a sketch example, corner marking,

Section of the state of Montana.
Certification must be signed and sealed by Land Surveyor registered in the State of Montana.
Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

Corner East 1/2 cor, Section 24, T. 24N, R. 5W P.M.M. Teton County

RECORD: (BLM DEPENDENT RESURVEY, 1955) Set an iron post, 30 ins. long, 2¹/₂ ins. diam., 28 ins. in the ground, with brass cap mkd.



raise a mound of stone, 3 ft. base, $1\frac{1}{2}$ ft. high, W. of the cor. post and bury the orig. stone alongside the cor. post.

This survey found a brass cap as described above, with FOUND: rock mound scattered. Brass cap is located 0.5ft. north of an east-west fence (the south R/W fence of a County road), and is flush with the ground.

Survey completed Dec. , 1989.

x x	CERTIFICATION
	certify the information shown herein is true and correct.
COUNTY ROAD (Paved) BRASS CAP 	Signature Ground Party Chief I. Ronald A. Lindseth certify that this Corner Record correctly represents work performed by me_or under my direction in compliance with the Corner- Recordation Act" (70-22-101, et seq. M.C.A.) Konald A. Jim Schlitte Signature of Surveyor & Seal Date 12/9/89 Reg. N8644S Sollf
SKETCH OF CORNER	Employer: Self
Office of Clerk and Recorder, County of	$_$. This "corner Sec. 24, T24N, R5W
was noted on the cross-index plat and is assigned page No.	, in
book No, County Official	
Cross Index NoT. 24N R. 5W PMM corner this sheet	
Adopted July 1, 1981, Montana Board of Professional En	gineers & Land Surveyors P-25