CERTIFIED LAND CORNER RECORDATION

DESCRIPTION OF CORNER EVIDENCE FOUND, AND ORIGINAL RECORD (IF KNOWN)

No evidence found.

DESCRIPTION OF MONUMENT AND ACCESSORIES ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

Corner set by 5" x 24" rebar w/cap at corner location.

Date of work: 2/2/76

Accessories: % etxnxilxandxdinexinx@ attmnwaadxtreexN7000 Set 1 x 12" rebar North 10.00 feet.

Set ½ " Ø x 12" rebar West 10.00 feet.

SKETCH, WITH COURSE AND DISTANCE TO ADJACENT CORNERS IF DETERMINED IN THIS SURVEY.

(MAY SKETCH OR PASTE REPRODUCTION ON REVERSE SIDE.)




DIAGRAM OF CORNER: Surveyor's Seal T24N,R5W,MPM certify that the information shown herein is true and correct. 211 7 Signature of Ground Party Chief Sec.24 3 Sec.23 Cor. I, Robert E. Findorff certify that I have carefully performed or reviewed the work done on the diagrammed corner as reported on this recordation form and approve the same. Corner recorded on the sheet Findorff Signature of Surveyor 3976 ES Registration Number

Office of Clerk and Recorder, County of Deton	323865
This "corner record" was filed for record on the 25 day of	
assigned page No, in book No	Gross Index No. P-21 T. 24 N R. 50 Mer.
Form 125—41328	Cross Index No. P-21 T 24N R 5W Mer.
	7603