Oraginal autors subsequents record area to ovariant up contrat promoti.
Description of evidence found, note discrepancies in the record.
Description of monument and accessories set to perpetuate the corner position.
Stetch of corner, show all pertinent data.
Certification must be signed and sealed by Land Surveyor licensed in the State of Montana.
Fill in index information and show the corner's approximate location within the section diagram.

## CERTIFIED CORNER RECORDATION

Corner: <u>SW Corner</u>	<u>Section 34 T. 25N R. 21W </u> P.M.M. L <u>ake County</u>
ORIGINAL RECORD:	Set 12"x10"x8" flint stone.
EMDENCE FOUND:	No evidence of original stone or accessories found. I find a 3/4" steel rod.
DISCUSSION:	3/4" steel rod shown as section corner on COS 2597. Origin of found steel rod unknown.
PERPETUATION:	See sketch below.





\* No fence running west or south from found monument.

annum

	JOHN M. DUFFEY 15624LS SURVEY
SKETCH: show enough information to clearly identify the corner (use back	if needed). • Location in Sec. 34
504113 CORNER Pages: 0	Certifications
STATE OF MONTANA LAKE COUNTY	John M. Duffey
RECORDED: 01/06/2010 4:15 KOI: CORNER	I, <u>John M. Duffey</u> certify that the work represented herein was faithfully performed.
RUTH E. HODGES CLERK AND RECORDER	Signature of Ground Party Chief
in Book No	Date: 1/6/2010 Lic. No. 15624LS Employer: Duffey Land Surveying
Adopted November 4, 2004, Montana Board of Professi	ional Engineers & Professional Land Surveyors 📿 —12