Lake Co.

## CERTIFIED LAND CORNER RECORDATION -

DESCRIPTION OF CORNER EVIDENCE FOUND, AND ORIGINAL RECORD (IF KNOWN)

FOUND A 2" PIPE WITH BRASS CAP! NO ORIGINAL EVIDENCE FOUND!

·	ÉR	
DES	PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:	
	Date of work:  FD. 2" Pipe With  BRASS CAP!	
	POLE. #D49442 CSEN SEC. WAIL IN CORNER OF GARAGE	
SKETCH, WITH COURS (MA	SE AND DISTANCE TO ADJACENT CORNERS IF DETERMINED IN THIS SURVEY.  AY SKETCH OR PASTE REPRODUCTION ON REVERSE SIDE.)	
	1327.25- 1327.25- 1327.25- 1327.25- 1327.25-	
. Surveyor's Seal	DIAGRAM OF CORNER:  certify that the information shown berein is true and N.	_
	Signature of Ground Party Chief  1. C. W. Doyle  1. certify that I have carefully performed or reviewed the work done on the diagrammed corner as reported on this recordation form and approve the same.	
	Signature of Surveyor  T26N RI 9W	
	2516-S Registration Number	
e of Clerk and Recorder, County	of Lake, State of Montana	_
"corner record" was filed for rec	book NG-796  By Slave County Official  Cross Index No. 219.58A. M.  at 9:58A. M.  Ethel M. Harding, Lake County Clerk & Recorder  By Slave County Official  Cross Index No. 219.58A. M.  Deputy  County Official	
· /a	Gross rider research T. R. R. Mer,	