## INSTRUCTIONS

- INSTRUCTIONS 1. Original and/or subsequent record used to evaluate the corner position 2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated corners

- conners.
  3. Description of monument and accessories set to perpetuate the corner position.
  4. Sketch of corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.
  5. Certification must be signed and sealed by Land Surveyor registered in the State of Montana.
  6. Fill in Cross Index & Section Diagram at bottom of sheet.

## CERTIFIED CORNER RECORDATION

Corner Sections <u>24 & 25 T. 26 N.</u> R. <u>33 W.</u> P.M.M. <u>Sanders</u> County

ORIG <b>INAL</b> RECORD:	(G.L.O.) Set a cedar post, 3 ft. long & 3 ins. square, 24 ins. in the ground, for A tamarack, 20 ins. diam., bears N 39° E, 262 lks dist. marked A tamarack 24 ins. diam., bears S 70° E, 30 lks. dist. marked	Y₄ sec. cor. marked S 24 on N. face from which: Y₄ S 24 BT. Y₄ S 25 BT.
SUBSEQUENT RECORD:	(1981 Recordation Form #158447) Surveyor Carl McMillen found part of org. cedar post in ground A 24" tamarack snag bears N 39° E, 172.92 feet, scribe visible Set 1" Iron Pipe and cap marked 4659S from which 4" Pine N 20° E, 5.9 ft. Fence Post East 5.7 ft.	
SUBSEQUENT RECORD:	<ul> <li>(1984 B.L.M. dependent resurvey)</li> <li>The ¼ sec. cor. of secs. 24 and 25, monumented with a ½ in. rebar, projecting 2 ins. above the ground, with plastic cap mkd. 4659S McMillen. from which the remains of the original bearing trees: <ul> <li>A stump, 24 ins. diam., bears N. 39° E., 262 lks. dist., mkd. with a rotted blaze.</li> <li>A stump hole, bears S. 70° E., 30 lks. dist., with a down log alongside, mkd. with a rotted blaze.</li> </ul> </li> <li>At the corner point: Set an aluminum post, 30 ins. long, 2 ½ ins. diam., 24 ins. in the ground, with aluminum cap mkd. (as shown below) from which: <ul> <li>A pine, 4 ins. diam., bears N. 32° E., 96 lks. dist., mkd. XBT.</li> <li>A pine, 20 ins. diam., bears S. 76 ¾° E., 91 lks. dist., mkd. ¼ S25 BT.</li> <li>A rebar, ⅔ in. diam., projecting 4 ins. above the ground, with plastic cap mkd. 3491S JJA, bears S. 74 ¾° W., 22 lks. dist.</li> </ul> </li> </ul>	
EVIDENCE FOUND:	Found 3 🔏 " Aluminum Cap, 0.45' above ground with old "T" post on west side. Found 1" Orange Plastic Cap "JA 3491 S" bears west, 14.45' dist.	
PERPETUATION:	Left corner as found and established a latitude and longitude for search purposes.	
Date of Survey: November, 2008. NAD 83 coordinates for this corner:		
view north of corner Latitude = 47°59'20.83725 "N Longitude = 115°47'35.05637 "W NOTE: These coordinates are to be used as a search tool only.		
		A HUND
	JACK LEG FENCE	CERTIFICATION I,
RTUL TO M	x x x x	certify the information shown herein is true and correct.
25 T26N R33W $25$ T/4 $\frac{24}{25}$	GRAVEL TWO WARNING TRACK ROAD SIGNS	Signature Ground Party Chief I, <u>Kurt A. Luebke</u> certify that this Corner Record correctly represents work performed by me or under my direction in compliance with the "Corner Recordation Act" (70-22-101, et seq., M.C.A.)
CAND MANN	(Not to Scale) SKETCH OF CORNER	Signature of Surveyor & Seal           Date:         12-10-2008         Reg. No.         13237 S            Employer:         DJ&A.P.C.
Office of Clerk and Recorder, County of Sanders . This "corner Sec. 24		
record" was filed for record on		
was noted on the cross index plat and is assigned page No. , in		
book No		
County Official  • - corner this sheet		

Cross Index No. R-23 T. 26 N. R. 33 W. PMM