INSTRUCTIONS

1. Original and/or subsequent record used to evaluate the corner position.

2. Description of evidence found, note discrepancies in record, state method of establishing lost or obliterated corners.

3. Description of monument and accessories set to perpetuate the corner position.

4. Sketch or corner, show all pertinent data which can best be shown in a sketch example,

corner marking, topography ties, position of accessories, etc.

5. Certification must be signed and sealed by Registered Land Surveyor in State of Montana.

6. Fill in Cross Index & Section Diagram at bottom of sheet.

## **CERTIFIED CORNER RECORDATION**

Corner	SW Cor.	Section	36	Τ.	28N	R.	3W	P.M.M.	Pondera	County

- 1. '1874' GLO Set a granite stone 16x12x 8 in. 11 inches in the ground for corner to Sections 1, 2, 35 and 36. Marked with a notch on the East and five on the West edges. Raised a mound of stone alongside.
- 2. Found and accepted a 1/2" rebar with a yellow plastic cap (3524ES) at intersection of gravel roads.
- 3. Set a 2-1/2" aluminum pipe with a 3-1/4" MDT aluminum cap 6" deep in gravel road in place of 1/2" rebar w/Y.P. cap.





INSTRUCTIONS 1. Original and/or subsequent record used to evaluate the corner position. 2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated corners. 3. Description of monument and accessories set to perpetuate the corner position. 4. Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc. 5. Certification must be signed and sealed by Registered Land Surveyor in State of Montana. 6. Fill in Cross Index & Section Diagram at bottom of sheet.							
Corner <u>Sec</u>	CERTIFIED CORNER RECORDATION35 3628 N.Cor.2 1T.27 N.R.3 W.P.M.M.PonderaCounty						
GLO RECORD:	(1874) Set a granite stone 16x12x8 ins., 11 inches in the ground for corner to Sections 1, 2, 35 and 36, marked with one notch on the east and five notches on the west edges and raised a mound of stone alongside.						
EVIDENCE FOU	ND: Found a 40D spike in intersection of east-west road and road to north. Origin unknown.						

Man NT VILLIAM W WEIKEL 4731 S TERED SURV

un in

ŧ

A	CERTIFICATION I Certify the information shown herein is true and correct.			
STOIRT				
FOUND 40D SPIRE SKETCH OF CORNER	Signature Ground Party Chief I. William W. Weikel certify that this Corner Record correctly represents work performed by me or under by direction in compliance with the "Corner Recordation Act" (7022-101, et seq., M.D.A.) Signature of Surveyor & Seal Date: 1/84Reg. No. 4731S Employer: Sorenson & Company			
Office of Clerk and Recorder, County of Pondera	This ''corner Sec. 35			
record" was filed for record on the	day of 19 ,			
was noted on the cross-index plat and is assigned page No.	, in			
book No County Offi				
Cross Index No. <u>8-21</u> 2-21	т. <mark>28N в. 3W</mark> рмм ● - corner this sheet 27N 3W			

-