CERTIFIED LAND CORNER RECORDATION

Corner	South	east,	Section	Corner	Sec.5	Т	28 N	P	39	Е	Р.М.М.
						··-	*	11	00	<u> </u>	r . Ivi . Ivi .

<u>G.L.O. Record</u> <u>80.30 The corner of section 4,5,8and 9, marked by the remains of the original monument, a broken limestone of indeterminate size, alongside which is a driven steel axle shaft 1" in diameter, buried 24 ins. below the</u> surface of the graded road. At the corner point, set an iron post 3 ft. long 2 ins. diameter 48 ins. in the ground, with brass cap marked.

_JK 1 PAGE 459

from which an iron post 3 ft. long 2" diameter set 34" in the ground for reference monument bears N45°E 71 lks. dist. with brass cap marked S4RM1946 and an arrow pointing toward the corner. An iron post 3 ft. long 2 ins. diameter set 27 ins. in the ground for reference monument bears S45°N, 81 1ks. dist. marked S8RM1946.

1

Evidence Found

The corner in \emptyset of county road 2" bury marked as stated. The RM's located were found 37.2" North and South of the corner rather than at 45° as stated. The iron post was 1" in lieu of 2" for the R.M. one (N) R.M. was marked S5RM1946 and the South RM was marked S9RM1946. The

