27617

P.M.M.

Ж

CERTIFIED LAND CORNER RECORDATION

E SN Corner of Section 29 T. 28 N ..., R. 40E

Corner_

	joining lands at the time the original survey was executed. At the corner point,
	Set an iron post, 3 ft ong, 2 ins. diam, 34 ins. in the ground, with brass cap mkd. S29 S28 S32 S33
	1946 from which an iron post, 4 ins diameter, projecting 12° above ground with standard bronze cap mkd. for a B.M. of the U.S. Bureau of Reclamation, elev 2081.58 ft., bears N 70 lks. dist.
	A brass tablet, 3 inches diam., imbedded in the N. headwall of bridge- aboutment, bears S 1-00W, 6 chains distant. the brass tablet has been marked, but the only remaining figures are badly battered.
]	EVIDENCE FOUND The iron post and brass cap marked as stated, and the fences as described. The RMs were evident, but the one on the canal bridge headwall was missing, as the concrete wall had failed, but the distance to the headwall agreed. No additional RM's were set.
	I, D. C. Beckman certify that the information shown herein is true and correct.
	D. C. Berlaman Signature of Ground Party Chief
	I, D. C. Beckman certify that I have carefully performed or reviewed the work done on the diagrammed corner as reported on this recordation form and approve the same.
	D. C. Berkmon Signature of Surveyor
	<u>23 JAN 1980 NON 7889</u> ES Date Registration Number

<u>GLO RECORD</u> The cor. of sec. 28,29,32, and 33, marked by the corner post of fence bearing N. and E. This post occupies the original corner position; it was identified by Adam Lenz, a settler who occupied ad-

DIAGRAM OF CORNER	BECKMAN 889ES
STATE OF MONTANA Office of Clerk and Recorder, County of VALLEY	AND SUCCESSION SUCCESSION
This "corner record" was filed for record on the <u>25th</u> day at 2:30 P.M. <u>114</u> in book No. <u>1</u> Corner Recordations FEE:\$1.50 Pd. 7296 RET: File.	of <u>JANUARY</u> 19 <u>80</u> , was noted on the cross-index plat . <u>Kany Jaw Eccle</u> County Official <u>Many City</u> Deputy <u>Cross Index No. V, 9 T. 28 N R. 40E</u> Mer.
21	7617