CERTIFIED LAND CORNER RECORDATION

DESCRIPTION OF CORNER EVIDENCE FOUND, AND ORIGINAL RECORD (IF KNOWN)

Evidence Found: At the Quarter corner of Section 12 and 7, we found an 1 3/4" Iron pipe with an 11/2" lead cap with no marks buried 4" at the4 intersection of the South edge of the railroad service road and Centerline of an approach from the South. The original monument was not found, T.33N., Sec. 12 R.6W., Sec. 7 R.5W.

DESCRIPTION OF MONUMENT AND ACCESSORIES ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:


Date of work: 7-16-91

Set: From the Quarter corner a nail in an AL Tag (45-4 LP-P, 1956) on power pole 7S7 bears S25°W, 70.4 feet. A nail in an AL Tag (45-5, LP-PA, 8, 1982) on power pole 7S8 bears N53°W, 37.2'.

We hung survey monument signs on both power poles.


SKETCH, WITH COURSE AND DISTANCE TO ADJACENT CORNERS IF DETERMINED IN THIS SURVEY.

(MAY SKETCH OR PASTE REPRODUCTION ON REVERSE SIDE.)



CPOWER Pale DIAGRAM OF CORNER: I, Souls certify that the information shown herein is true and Surveyor's Seal 33N N. correct. Signature of Ground Party Chief S 7 512 Stomas certify that I have carefully performed or reviewed the work done on the diagrammed corner as reported on this recordation form and approve the same. X = Corner recorded on the sheet (lunus) Signature of Surveyor 82385 Registration Number

Office of Clerk and Recorder, County of County Office of County Off



STATE OF MONTANA County of Glacier Filed for Record this	
Clara Henderson	
By AK Barson County Recorder	
Return to	
Fee \$	