## CERTIFIED LAND CORNER RECORDATION

DESCRIPTION OF CORNER EVIDENCE FOUND, AND ORIGINAL RECORD (IF KNOWN)

Evidence Found: At the Section corner common to Sections 1,6,7 and 12, we found North - South gravel road, (6th Ave. NE), fence line running East. At intersection of the road and fence we found 5/8" rebar with destroyed yellow plastic cap burried 6" in center of road. T.33N., Sec.1 & 12, R.6W., Sec. 6 & 7, R.5W.

> DESCRIPTION OF MONUMENT AND ACCESSORIES ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

> > Date of work: 7-16-91

33 N

R.

T.

5W Mer

Set: We set a new yellow plastic cap stamped "Triangle Eng. RLS 8238," on rebar.

From the corner; Center top of fire hydrant bears N14<sup>0</sup>W, 54.7 Feet Nail with spinner in West face of corner fence post bears S88<sup>0</sup>E, 30.6 Feet., We attached Survey monument signs to the fence post and fire hydrant.

SKETCH, WITH COURSE AND DISTANCE TO ADJACENT CORNERS IF DETERMINED IN THIS SURVEY. (MAY SKETCH OR PASTE REPRODUCTION ON REVERSE SIDE.)



DIAGRAM OF CORNER: I, Guy Dubois . certify that the information shown herein is true and T33N Surveyor's Seal N. 56 correct. 51 Signature of Ground Party Chief SIZ 57 Kuszett THOMASL. З 3 I. certify that I have carefully performed or reviewed the work done on the diagrammed corner as reported on this Pec Ŕ recordation form and approve the same. = Corner recorded on the sheet my aunt Signature of Surveyor 8238 S Registration Number Office of Clerk and Recorder, County of ..... 19.91, was noted on the cross-index plat and i: This "corner record" was filed for record on the 24 497, in book No. 48 Marco assigned page No ..... son A ....  $\sim$ County Official

Cross Index No ...

at 3 Form 125-7887



227255

STATE OF MONTANA County of Glacier }ss Filed for Record this day of A.D. 19 CIA 9 4:2 5 at o'clock М Dook and records of on Page 4 4  $\Lambda a$ Clara Henderson County Recorder By an Deputy C Return to Fee \$ -