		 Original and/or subset Description of evidence Description of monum Sketch of corner, she topography ties, position Certification must be Fill in Cross Index & 	te found, note discre- nent and accessories w all pertinent da of accessories, etc signed and sealed t	epancies in th s set to perpe ta which can by Land Surve	e corner position. e record, state me tuate the corner p best be shown h eyor registered in	osition. n a sketch example, c	orner marking,	
-		CER	TIFIED C	ORNE	R RECO	RDATION		
Corner .	Northeast	Section 11	`T	35N	R ^{48E}	P.M.M.	Daniels	County
						•		

· · · · · · · ·

- Didn't have copy of original notes. Had copy of G.L.O. Plat.
- 2. Found East-West trail. Didn't find a monument at this corner. Set monument on centerline of trail and at proportionate measure between corners. Best evidence of location of this corner.
- 3. Set #5 rebar and 2" aluminum cap stamped:



E + 25'07 TAAIL SKETCH OF CORNER	I certify the information shown herein is true and correct. RICHARD H. Signature field/shown herein is true and correct. RICHARD H. Signature field/shown and parts Chiefs I. Richard H. DDd S Q- certify that the Corner Record correctly represents work performed by me or under by base fibri is coordinate with the "Corner Recordation Act = 10 (200), et sen. M. (10.) Signature of Surveyor & Seal Date: 10/90 Reg. No. 9018S Employer: Interstate Engineering, Inc.
Office of Clerk and Recorder, County of Daniels	This "corner Sec. 11
record" was filed for record on <u>October 29, 1990 at 11:05</u> was noted on the cross-index plat and is assigned page No.	
book No County Office	elal
Fee: D.H. Cross Index No. <u>E-21</u> Adopted July 1, 1981, Montana Board of Professional Eng	<u>35N</u> R. <u>48E</u> PMM gineers & Land Surveyors