INSTRUCTIONS Original and/or supsequent record used to evaluate the corner position.
Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated

Description of evidence found, note discrepancies in the receive, series and the corners.
Description of monument and accessories set to perpetuate the corner position.
Sketch of corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.
Certification must be signed and sealed by Land Surveyor registered in the State of Montana.
Fill in Cross Index & Section Diagram at bottom of sheet.

## **CERTIFIED CORNER RECORDATION**

\_\_\_\_P.M.M. \_\_\_\_Sheridan Corner\_Southeast Section 8 T. <sup>35N</sup> \_\_\_\_R.\_\_<sup>54E</sup> \_\_County

- Original survey set a granite stone 18x10x8 inches, 12 inches in the ground, for corner of Sections 8, 9, 16 and 17, marked with 4 notches on S. and E. edges; dig pits, 18x18x12 ins. 1. in each Section,  $5\frac{1}{2}$  ft. distance, and raise a mound of earth, 4 ft. base, 2 ft. high W. of corner.
- 2. Found original stone in place. Set #5 rebar and 2" cap on east side of stone.

Stone is in pasture on south side of washed out ravine. 3.

		CERTIE	FICATION	
Z SZA ZUZZALA Noosalari Vits	ALUA.	I. <u>RichardHHM</u> certify that this Cornect queet as by me of under my direction Recordation Act, 2002, 101, est	Th om Thom precify represents work performed in opportents with the "Corner 10, 10, 10, 10, 10, 10, 10, 10, 10, 10,	
SKETCH OF CORNER		Employer: Interstat	ce Engineering,	Inc
Office of Clerk and Recorder, Count record" was filed for record on	y of Sheridan June 26, 1996	This "corner at ///ac Am	Sec. 8	
was noted on the cross-index plat ar	nd is assigned page No	, in		
book No. $287$	MiltonE	Bene Dang		
444384	Cross Index NoJ-9	T. 35N R. 54E PMM	• - corner this sheet	
Adopted July 1, 19	81, Montana Board of Professiona	al Engineers & Land Surveyors		