INSTRUCTIONS	sition.
<ol> <li>Description of evidence found, note discrepancies in the record, sta corners.</li> <li>Description of monument and accessories set to perpetuate the cord. Sketch or corner, show all pertinent data which can best be sho topography ties, position of accessories, etc.</li> <li>Certification must be signed and sealed by Registered Land Surver 6. Fill in Cross Index &amp; Section Diagram at bottom of sheet.</li> </ol>	ate method of establishing lost or obliterated rner position. own in a sketch example, corner marking,
CERTIFIED CORNER REC	CORDATION
Corner NORTH 1/4 CORNER SECTION 3 T. 34N R.	
() Used GLO Notes and guad man to sa	
For found - could not find any evin	
3) Set MDOH Aluminum pipe and 3" Alu coordination of section breakdown	
section breakdown	, cased off
	N
50'	
0 - MOOH SURVEY MARKER POST	
FARM ROAD	
93'	AND I STATE
	ANT ROMO
	Jen /
O- MOOT CONTROL	
TRAVERSE POINT	
3" ALUMINUM CAP	
ALTAND ST	CERTIFICATION
	I. DAN KENCZKA MINIMUM certifs the information shown borein structure connect.
(0 34 Va	Signa Birey Ground Party Chief
4 turne 3 5 5 5	I. JALK R. TOSHERACK R.
HAR GOIZES TE	by me or under by direction in comptants work primined Recordation Act'' (70-2210), ct see (M.D.A.)
Here GOIBES AC	Signature of Berever & Scal Alimin
SKETCH OF CORNER	Date: 5/17/95 Reg. No. (80)3ESIM
Office of Clerk and Recorder, County of Meridan	_, This "corner Sec. 3
record" was filed for record on the July 5, 1995 at 1:00 pr	1_ day of 19
was noted on the cross-index plat and is assigned page No.	
book No. 240 442221 Multon & Seuland by Service for	
Cross Index No. <u>A-15</u> T. <u>34N R. 54E PMM</u> Corner this shoot	