



## **CERTIFIED LAND CORNER RECORDATION**

DESCRIPTION OF CORNER EVIDENCE FOUND, AND ORIGINAL RECORD (IF KNOWN)

From: "Subdivisional lines of T9S, R8E". 1883. (1697-458)

- "Set a magnetite stone 16x14x10 in., 11 ins. in the ground marked ‡ on W face and raised a mound of stone alongside".
- Found: At proportionate distance between NW and SW section corners: large sidecast boulders immediately below a quarry road. Assumed that original corner lost.



SKETCH, WITH COURSE AND DISTANCE TO ADJACENT CORNERS IF DETERMINED IN THIS SURVEY. (MAY SKETCH OR PASTE REPRODUCTION ON REVERSE SIDE.)

See drawing on reverse of corner record for NW corner record of Section 14.

		DIAGRAM OF CORNER:
Surveyor's Seal	I certify that the information shown herein is true and correct.	T9S N. R8E MPM
	Signature of Ground Party Chief	15 14
	I, <u>Henry A. Rate</u> certify that I have carefully performed or reviewed the work done on the diagrammed corner as reported on this recordation form and approve the same.	 1/4
		= Corner recorded on the sheet
	Signature of Surveyor	
	3716S Registration Number	
Office of Clerk and Recorder, Cour	nty of Park 3.42572	
	record on the 57 day of October 1976, was	s noted on the cross-index plat and is
assigned page No. 16.		<u>set monical</u> try Official
Form 125-3690 Dec - 50 acu		r