INSTRUCTIONS Original and/or subsequent record used to evaluate the corner position.
 Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated



Description of evidence round, note discrepances a matrix corners.
 Description of monument and accessories set to perpetuate the corner position.
 Sketch of corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.
 Certification must be slgned and sealed by Land Surveyor registered in the State of Montana.
 Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

Corner <u>NE corner Sec. 16</u>

_____T.__<u>9 S.____</u>R.<u>8 E.____</u>P.M.M.__<u>Park__</u>

County

In July 1883 U.S. Deputy Surveyor Rodney W. Page set a Sandstone 20"x12"x10" 1. 15" in the ground for a corner to sections 9, 10, 15 and 16 marked 4 notches on south and 3 on east edges and raised a mound of stone along side. Pits were impractical.

In 1916 George F. Rigby and Clarence K. Streit in a retracement of the line between sections 10 and 15, ran west between said sections and intersected the north-south line 10 lks. north of the corner of sections 9, 10, 15 and 16 which was a Granite Stone 8"x8"x10" above ground, firmly set, marked as described by the surveyor general and at that time they rebuilt the mound of stone, 2' base, 1¹2' high North of corner.

- I found a mound of stone 2' base at the approximate G.L.O. distance east, west and north. I accepted the mound of stone as the same mound as set in the 1916 retracement survey. After an exhausting search of the area I found no trace of the section corner stone. Therefore, I set an aluminum monument as 2. described below, on the South edge of the mound of stone. I then rebuilt the mound of stone.
- Set $2\frac{1}{2}x30$ " aluminum pipe 27" in the ground with 3 3/4" aluminum cap marked 3. as indicated below.

Set ½"x24" rebar w/alum. cap S62 39'W, 17.7'marked RM 1

Set ½"x24" rebar w/alum. cap N25 Ol'W, 20.6 marked RM 2

Rebar w/alum. cap		Marks on monument set for section	CERTIFICATION	
0			<u>1, Steven J. Barber</u>	
125		corner –	certify the information shown h	erein is true and correct.
To les	ware at at an a	corner	steven A	HTT NING
S - S - S	mound of stone		Signature Gro	hind Party Chief
Log.	- -	T9S R8E	I. Michael D. Weldon (1990)	
New Yes				Precily represents work performed
		<u>\$9 \$10</u>	by me or under my direction	in compliance with the "Corner
362 39 6		S16 S15	Recordation Act" 79-22-101, et s	seq., M.C.A.)
56977		\ 7692S/	michaek	A. Cercland
Rebar		1984	Signature of	Surveyor & Seal
	lum mon co	+	Date: 3/84 Reg. No.	7692 S : 612
w/alum. cap	∧alum. mon. se	of mound of stone		
	SKETCH OF CORNEL	of mound of stone 180738	Employer: U.S. Fores	t service
Office of Claub and Dee	and an Country of	(+) - , ek	This floornon	Sec. 16
Office of Clerk and Rec	order, County of _	Jack	This "corner	- Jan I
record'' was filed for re	ecord on	1, 1984	@ 12:18 P.M	
	0		H /	16
was noted on the cross-	index plat and is as	ssigned page No.	<u>76</u> , in	├-+ - ¹
		$\langle \rangle$		
book No	<u> </u>	- tome offe	ming	
42		() County Offic		
no fee				I have been a second se
	Cros	s Index No. <u>J-13</u> T	<u>95 r. 8E</u> pmm	 corner this sheet
			I D T and Company	

Adopted July 1, 1981, Montana Board of Professional Engineers & Land Surveyors