

July 1978 - Certificate of Survey No. 393, as filed by Robert Babb, 4523ES. Found Mound of Rocks with Scribed Post. Set rebar w/alum cap marked N  $\frac{1}{2}$  24.

- 2) Found the monument according to Certificate of Survey No. 393. I do not know what prompted Mr. Babb to accept a scribed post when the record does not state such. A diligent search was made in the area for evidence of the original stone. None was found. Measurement to adjacent corners v. retracement record indicates that the rebar is within 6 ft.+/-, of a record position. I accept Mr. Babb's corner position as the best evidence of the original corner position.
- 3) At the position occupied by the found rebar, set a 2½"x 30" aluminum pipe, 24 ins. in the ground, with 3½" aluminum cap marked as shown below. Place the rebar inside the pipe and place a 1" magnetic reference module under pipe.

Raise a mound of stone 3½ ft. base by 2 ft. high. Set a galvanized steel post with Land Survey Monument sign, alongside corner. A granite boulder, 3 ft. diam by 2½ ft. high, bears northerly 4 ft.

14 3/3 14 3/3 14175 1988	I, Steves To NEAM certify the promatient shown fit ANTHONY Signature Cro BACHMA I, Antthony BACHMA I, Antthony BACHMA I, Antthony BACHMA Certify that biscorner Record co by med water row direction Recorder to Art (2020) of the Recorder to Art (20	und Parts Chef
SKETCH OF CORNER	Employer.	
Office of Clerk and Recorder, County of <u>Park</u> record" was filed for record on <u>March</u> 28, 1989 2	This ''corner : / 6_ <i>P.M</i>	Sec. 24
book No. <u>One</u> The Fee <b>20'7'755</b> NANCY HOWIESON County Offic N-23		

Copy. 50 4

Adopted July 1, 1981, Montana Board of Professional Engineers & Land Surveyors