INSTRUCTIONS
riginal and/or subsequent record used to evaluate the corner position.
2. Description of evidence found, note discrepancies in the record, state method of establishing lost or object ated
corners.
Description of monument and accessories set to perpetuate the corner position.
4. Sketch of corner, show all pertinent data which can best be shown in a sketch example, corner marking,
topography ties, position of accessories, etc.
5. Certification must be signed and sealed by Land Surveyor registered in the State of Montana.
6. Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

Corner M.C. Lt. to Frac. Secs. 8+17 T. 95 R. 8E P.M.M. Park County

FROM: V103, P20: "Left bank of Yellowstone River. Set a granite stone 14x12x10 ins., 9 ins. in the ground for meander corner to frac't Secs. 8 and 17 marked M.C. and raised a mound of stones 2 ft. high, 4 1/2 ft. base alongside."

FOUND: Brass Cap on 1 in. pipe, 6 ins. up. Set in 1933 by W. R. Bandy who did not find original stone. Brass Cap is on lip of river bank in small cairn.

See attached sheet (portion of C/S 1040) for proximate ties.

Brass Cap marked:

J.S.G. T9S 58 wc 517 R8E 1933

	CERTIFICATION
M.C. Lt T95	I,
58 R8E 517	Signature Ground Party Chief I. <u>Henry A. Rate</u> certify that this Corner Record correctly represents work performed by me briunder my direction in compliance with the "Corner Recordation Act" (70-20101, et eq. M.C.A.) Signature of Surveyor & Seal Date: 2/15/96 Reg. No. 37165
SKETCH OF CORNER	Employer:
Office of Clerk and Recorder, County of Park record'' was filed for record on Opril 23 1996	$\begin{array}{c} \text{Sec. 17} \\ \hline 4 \text{ Sign} \end{array}$
was noted on the cross-index plat and is assigned page No	, in
book No. One (lenus) Nel County Officie	
252506 Cross Index No. <u>J8</u> T. Adopted July 1, 1981, Montana Board of Professional Eng	<u>95</u> R. <u>8E</u> PMM incers & Land Surveyors

