CERTIFIED CORNER RECORDATION

Corner Sections 5/6/7/8

T. 9S R. 8E P.M.M. Park County

1. GLO Record:

R.W. Page, July, 1883:

North Bet. Secs. 7 and 8. Var. 19°E. Descend.

28.75 Cross stream 10 lks. wide, course N. 60°E. Thence rolling.

- 33.40 Road from sawmill, course N.60°E.
- 40. Set sandstone 12x8x8 in. in the ground for 1/4 sec. cor. marked 1/4 on W. face and raised a mound of stone alongside. Pits impracticable.
- 80. Set sandstone 12x8x8 in. 8 in. in the ground for cor. to Secs. 5,6,7 and 8 marked 5 notches on S. and E. edges and raisec a mound of stone alongside. Pits impracticable.

2. Evidence found, December, 1999:

Found a stone measuring $7^{\circ}x6 \frac{1}{2}^{\circ}x 14^{\circ}$ (7" above the ground) with 5 faint slashes on the East side and 2 slashes on the South side. The stone was fractured on the top West side.

3. Perpetuation, December 13, 1999:

Set a $3\frac{1}{4}$ " dome top aluminum monument with a magnet beneath cap and a 2 3/8" O.D. x 30" long aluminum pipe stem with splayed feet with cap 5" above ground level. Set a steel fence post approx. 1.5 ft. East of monument. Built a 3' diam. cairn of rock around the monument. Cap marked as follows:



<u>SEE_REVERSE_SIDE</u>	Certification I certify the information short Heterois true and correct. I
Sketch of Corner	Date: 9/8/00 Reg. No. 10355 LS Employer: Thomas J. Hallin, 287 ES .
Office of Clerk and Recorder, County of Park This "c record" was filed for record on Left 18, 2000 @ [2:26] was noted on the cross-index plat and is assigned page. No /06 in book No Deputy 285304 Cross Index No R8EPMM	

Adapted July 1, 1981, Montana Board of Professional Engineers & Land Surveyors



